

# PERSONNEL QUALIFICATION AND ENVIRONMENTAL MONITORING

ARL TEST SERVICES	USP TESTING REQUIREMENTS	USP <797> CATEGORY 1 AND 2	USP <797> CATEGORY 3
	Visual Observation of hand hygiene and garbing	Once Every 6 months	Once Every 3 months
✓	Gloved Fingertip and thumb sampling	Once Every 6 months	Once Every 3 months
✓	Media Fill Testing	Once Every 6 months	Once Every 3 months
✓	Post Media-fill surface sampling	After Each Media Fill Competency	After Each Media Fill Competency
✓	Surface sampling	Monthly	Weekly
✓	Viable Air Sampling	Once Every 6 months	Monthly

\*For Category 3 CSPs, refer to USP <797> for additional surface sampling requirements.

**REQUEST A QUOTE**